







PORTE COULISSANTE À GALANDAGE





ACCESSORI NON FORNITI DA PAIL
ACCESSORIES NOT SUPPLIED BY PAIL
ACCESSOIRES NON FOURNIS PAR PAIL



1





2





3








4




5






10

LATO INTERNO - INTERNAL SIDE - COTE INTERIEUR

11

LATO INTERNO - INTERNAL SIDE - COTE INTERIEUR

12

LATO INTERNO - INTERNAL SIDE - COTE INTERIEUR

13